If your model is not listed, there is no update available.
Please visit your local TOSHIBA Support website or Support Forum for further information.

**Firmware update information for
Consumer Products (TV's, TV-Combis and BD-Players)**

TOSHIBA
Leading Innovation >>>

Product Category:	Model year:	Size:	Modelname:	Countrycode:	Latest Version for Download	Network update available ?	Latest Version for Network update	Release Notes (Fixed problems):
TV	2009 A/B	32/37/42	AV623D		2.1.77.2	---	---	
		32/37/42	AV625D		2.1.77.2	---	---	
		32/37/42	AV633D		2.1.77.2	---	---	
		32/37/42	AV635D		2.1.77.2	---	---	
		32/37	AV636D		2.1.77.2	---	---	
		40	LV665P		2.1.77.2	---	---	
		32/40	LV665D		2.1.77.2	---	---	
		32/40	LV675D		2.1.77.2	---	---	
		32/40	LV685D		2.1.77.2	---	---	
		32/37/42	RV623D		2.1.77.2	---	---	
		32/37/42	RV625D		2.1.77.2	---	---	
		32/37/42	RV626D		2.1.77.2	---	---	
		32/37/42	RV633D		2.1.77.2	---	---	
		32/37/42	RV635D		2.1.77.2	---	---	HDMI Echo symtom fixed --> Link
		32/37/42	RV636D		2.1.77.2	---	---	
		32/37/42	RV665D		2.1.77.2	---	---	
		32/37/42	RV675D		2.1.77.2	---	---	
		32/37/42	RV685D		2.1.77.2	---	---	
		46/55	SV675D		2.2.77.2	---	---	
		46/55	SV685D		2.2.77.2	---	---	
		32/37/46	XV625D		2.1.77.2	---	---	
		42	XV626D		2.1.77.2	---	---	
		42	XV632D		2.1.77.2	---	---	
		42	XV633D		2.1.77.2	---	---	
		32/37/46	XV635D		2.1.77.2	---	---	
		42	XV636D		2.1.77.2	---	---	
		42/47/55	ZV625D		2.1.77.2	---	---	
		42/47/55	ZV635D		2.1.77.2	---	---	
TV	2010 A	32/37/40	RV733	F	10.1.41.9	---	---	
		32/40/46	SL733	F	10.1.41.9	---	---	- Corruption in channel list
		32/40/46	SL736	F	10.1.41.9	---	---	- TV don't come back in last mode after AC power off/on
		32/40/46	VL733	F	10.1.41.9	✔	10.1.41.9	- YouTube XL link don't work
		32/37/40/46	XV733	F	10.1.41.9	---	---	
		32/37/40/46	MV732	G/R	10.1.59.6	---	---	
		32/37/40	RV733	B/G/R	10.1.59.6	---	---	- KDG CI+ CAM not working properly ("CAM removed/inserted message")
		32/40/46	SL733	B/G/R	10.1.59.6	---	---	- Corruption in channel list
		32/40/46	SL736	B/G/R	10.1.59.6	---	---	- TV don't come back in last mode after AC power off/on
		32/40/46	VL733	B/G/R	10.1.59.6	✔	10.1.59.6	- YouTube XL link don't work
		32/40/46	XV733	B/G/R	10.1.59.6	---	---	
		32/40/46	SL753	B	10.2.63.5	---	---	
		32	VL753	B	10.2.63.5	---	---	Fixed an issue with 1080i/p switching with BBC signal in UK
		37/40	RV753	B	10.2.63.5	---	---	
		32/37/40	RV743	G/R	10.3.57.12	✔	10.3.57.12	
		32/37/40	TV743	G/R	10.3.57.12	✔	10.3.57.12	- Loosing transponders in DVB-S channel list
		32/40/46	VL743	G/R	10.3.57.12	✔	10.3.57.12	- Corruption in channel list
		32/37/40/46	XV743	G/R	10.3.57.12	✔	10.3.57.12	- TV don't come back in last mode after AC power off/on
		32/40/46	YL743	G/R	10.3.57.12	✔	10.3.57.12	- YouTube XL link don't work
		32/37/40/46	ZV743	G/R	10.3.57.12	✔	10.3.57.12	
		40/46/55	WL753	F	10.4.41.9	✔	10.4.41.9	- Corruption in channel list
		40/46/55	WL753	G/R	10.4.59.5	✔	10.4.59.5	- TV don't come back in last mode after AC power off/on
		40/46/55	WL753	B	10.4.63.5	---	---	- YouTube XL link don't work
								Fixed an issue with 1080i/p switching with BBC signal in UK
		40/46/55	WL743	G/R	10.5.57.12	✔	10.5.57.12	- Loosing transponders in DVB-S channel list - Corruption in channel list

If your model is not listed, there is no update available.
Please visit your local TOSHIBA Support website or Support Forum for further information.

**Firmware update information for
Consumer Products (TV's, TV-Combis and BD-Players)**

TOSHIBA
Leading Innovation >>>

Product Category:	Model year:	Size:	Modelname:	Countrycode:	Latest Version for Download	Network update available ?	Latest Version for Network update	Release Notes (Fixed problems):
TV	2010 B	19/22/26/32/42	SL738	F/G/N/R	V.2.03	---	---	- preventive update for a "CI+" problem - reception problems in Italian DVB-T signal - problems with Italian "play.me" service
		40/46	VL758	B	17.1.24.12	✔	17.1.24.12	
		40/46	VL748	F/G/R	17.2.24.12	✔	17.2.24.12	
		40/46	XL748	F/G/R	17.2.24.12	✔	17.2.24.12	
		40/46/55	WL768	B/F/G	17.3.24.12	✔	17.3.24.12	
		40	WL768	B	17.3.24.17	---	---	Fixed an issue with 1080i/p switching with BBC signal in UK
		40/46/55	YL768	G	17.3.24.12	✔	17.3.24.12	
	2011 A	32	AV833	B/F/N	v1.57	---	---	
		32	AV833	G	v1.05	---	---	
		32	AV834	B	v1.57	---	---	
		32	AV834	G	v1.05	---	---	
		26/32	EL833	B/F/N	v1.57	---	---	
		26/32	EL833	G	v1.05	---	---	
		26/32	EL834	B	v1.57	---	---	
		26/32	EL834	G	v1.05	---	---	
		32/42	HL833	B/F/N	v1.57	---	---	
		32/42	HL833	G	v1.05	---	---	
		32/42	HL834	G	v1.05	---	---	
		32/40	LV833	B/F/N	v1.57	---	---	
		32/40	LV833	G	v1.05	---	---	
		32/37/42	RL833	G/R	17.8.37.1	✔	17.8.37.1	Fixed an issue with 1080i/p switching with BBC signal in UK
		32/37/42	RL853	B	17.9.39.1	✔	17.8.39.1	
		32/37/42	SL833	G	19.1.61.14	✔	19.1.61.14	v.61.14 fixed: - YouTube XL playback problems (wrong video scaling) - updated SAT transponder list - fixed a problem with SAT channel list corruption - fixed a problem in Danish STOFA network
		32/37/42	SL833	F/N	19.1.49.236	✔	19.1.41.236	
		32/37/42	SL833	R	19.1.61.7	✔	19.1.61.7	
		32/37/42/46	SL863	B/G	19.2.61.14	✔	19.2.61.14	
		32/37/42/46	SL863	F/N	19.2.49.236	✔	19.2.49.236	
		32/37/42/46	SL863	R	19.2.61.7	✔	19.2.61.7	
		32/37/42/46	UL863	B/G	19.3.61.14	✔	19.3.61.14	
		32/37/42/46	UL863	F/N	19.3.49.236	✔	19.3.49.236	
		32/37/42/46	UL863	R	19.3.61.7	✔	19.3.61.7	
		32/37/42/46	UL875	G	19.3.61.14	✔	19.3.61.14	
		42/47	VL863	B/G	19.4.61.14	✔	19.4.61.14	
		42/47	VL863	F/N	19.4.49.236	✔	19.4.49.236	
		42/47	VL863	R	19.4.61.7	✔	19.4.61.7	
		42/46/55	WL863	B/G	19.5.61.14	✔	**19.5.61.15**	v.61.15: re-enables MAXDOME playback, that will not work after June2013 with SW versions <=61.14. MAXDOME is only supported by WL863 based models and ZL2.
		42/46/55	WL863	F/N	19.5.49.236	✔	19.5.49.236	
		42/46/55	WL863	R	19.5.61.7	✔	19.5.61.7	
		42/46/55	YL863	B/G	19.5.61.14	✔	19.5.61.14	
		42/46/55	YL863	F/N	19.5.49.236	✔	19.5.49.236	
		42/46/55	YL863	R	19.5.61.7	✔	19.5.61.7	
		42/46/55	YL875	G	19.5.61.14	✔	19.5.61.14	
		55	ZL1	F/G/R	19.7.61.14	✔	19.7.61.14	
		46/55	ZL2	F/G/R	19.9.62.9	✔	19.9.62.9	

If your model is not listed, there is no update available.
Please visit your local TOSHIBA Support website or Support Forum for further information.

**Firmware update information for
Consumer Products (TV's, TV-Combis and BD-Players)**

TOSHIBA
Leading Innovation >>>

Product Category:	Model year:	Size:	Modelname:	Countrycode:	Latest Version for Download	Network update available ?	Latest Version for Network update	Release Notes (Fixed problems):
TV	2011 B	32/40	RL838	G/F	---	✔	6.4.0Y.1	Release notes for 6.4.xY.1: - Fixed an issue with HbbTV crashing. - Toshiba Places compatibility issues fixed
		32/40	RL858	B	---	✔	6.4.2Y.1	
		32/40	RL838	N	---	✔	6.4.2Y.1	
		32/40/46	TL838	G/F	---	✔	6.4.0Y.1	IMPORTANT: Please "RESET" your TV after the network Software update in order that the changes will be applied. Refer to the user manual on how to RESET the set to factory shipout condition.
		32/40/46	TL868	G/F	---	✔	6.4.0Y.1	
		32/40/47	TL868	B	---	✔	6.4.2Y.1	PLEASE NOTICE: individual channel list and personal settings will be deleted after a RESET.
		32/40/47	TL868	N	---	✔	6.4.4Y.1	
	2012 A	19	EL933	G	v116	---	---	v116: fixes a problem with wrong Polish TTX characters
		19	EL934	G	v116	---	---	
		19	EL933	RB	v1.25.02	---	---	
		23	EL933	G	v116	---	---	
		23	EL934	G	v116	---	---	
		23	EL933	RK	v1.25.02	---	---	
		26	EL933	B/G/RB	v1.25.02	---	---	1.25.02 fixed: - fixes problems with missing channels / corrupt channellist - fixes a problem with DVB-T demodulation in France
		26	EL934	G	v1.25.02	---	---	
		32	AV933	G/N/RB	v1.25.02	---	---	
		32	AV934	G/RB	v1.25.02	---	---	
		32	EL933	G/N/RB	v1.25.02	---	---	
		32	EL934	G/RB	v1.25.02	---	---	
		32	HL933	B/G/N/RK	v1.25.02	---	---	
		32	LV933	G/N/RB	v1.25.02	---	---	
		40	HL933	B/G/RK	v1.25.02	---	---	
		40	LV933	G/N/RB	v1.25.02	---	---	
		23/32/40	RL933/936	B/G/F/N	6.9.MD.1	✔	6.9.MD.1	6.9.MD.1 fixed: - fixed a problem with ON TIMER after Stdby, that did not work - improved stability for the symptom "no power up" after network update - add. German HD transponders for SAT
		23/32/40	RL933	R/RB	6.9.MD.1	✔	6.9.MD.1	
		32/40	RL953	B/N	6.9.MD.1	✔	6.9.MD.1	
		32/40	RL953	R/RB	6.9.9E.1	✔	6.9.9E.1	
		32/40	SL970	G	6.9.MD.1	✔	6.9.MD.1	IMPORTANT IMFORMATION: please RESET your TV after a FW-update via USB or network in order that the changes become acivated. Refer to the user manual on how to perform a RESET.
		32/40/46	TL933/ TL936	G/F	6.9.MD.1	✔	6.9.MD.1	
		32/40/46	TL933	R/RB	6.9.MD.1	✔	6.9.MD.1	
		32/40/46	TL963/ TL966	G/F	6.9.MD.1	✔	6.9.MD.1	
		32/40/46	TL963	R/RB	6.9.9E.1	✔	6.9.9E.1	
		32/40/46	UL975	G	6.9.MD.1	✔	6.9.MD.1	
		42/47/55	VL963	B/G/F/N	6.9.MD.1	✔	6.9.MD.1	
		42/47/55	VL963	R/RB	6.9.8E.1	✔	6.9.8E.1	
		42/47/55	XL975	G	6.9.MD.1	✔	6.9.MD.1	
	2012 B	19/22/32	BL502	B	v.0.6.8c	---	---	**Fixed instability problems with symptoms like:** - set does not power up, only front LED blinking (red/green) - empty or corrupted channel list - missing channels after inital scan
		32	BL505	B	v.0.6.8c	---	---	
		32	BV502	B	v.0.6.8c	---	---	
		32	BV504	B	v.0.6.8c	---	---	
		32	BV512	B	v.0.6.8c	---	---	
		32	BV702	B	v.0.6.8c	---	---	
		32	BV712	B	v.0.6.8c	---	---	
		19/23/26/32	KL933	R	v.0.6.8c	---	---	
		19/23/26/32	KL934	R	v.0.6.8c	---	---	

If your model is not listed, there is no update available.
Please visit your local TOSHIBA Support website or Support Forum for further information.

Firmware update information for
Consumer Products (TV's, TV-Combis and BD-Players)

TOSHIBA
Leading Innovation >>>

Product Category:	Model year:	Size:	Modelname:	Countrycode:	Latest Version for Download	Network update available ?	Latest Version for Network update	Release Notes (Fixed problems):
TV	2012B	32/40	RL938	F/G	7.0.28.16.1	✔	7.0.28.16.1	Release notes for 7.0.28.14.1:
		32/40	RL939	G	7.0.28.16.1	✔	7.0.28.16.1	- extended support of Media Player files - .tp (MPEG2 TS) / .div (DivX 3,4,5,6) / .xvid (Xvid) / .swf (Flash Video)
		32/40	RL958	B	7.0.28.16.1	✔	7.0.28.16.1	- WIDI 3.5 support
		32/40	SL980	G	7.0.28.16.1	✔	7.0.28.16.1	- approved for the use in the Ziggo network of NL
		40/46	TL938	G	7.0.28.16.1	✔	7.0.28.16.1	- fixed a subtitle problem in UK
		40/46	TL939	G	7.0.28.16.1	✔	7.0.28.16.1	- fixed a problem with subtitle of Canal ready network
		40/46	TL968	B/G	7.0.28.16.1	✔	7.0.28.16.1	
		42/47/55	WL968	B/F/G	7.0.28.16.1	✔	7.0.28.16.1	Additional information:
		40/46	UL985	G	7.0.28.16.1	✔	7.0.28.16.1	If you YouTube Leanback service doesn't work for you any longer, please update with this version !
		42/47/55	YL985	G	7.0.28.16.1	✔	7.0.28.16.1	
								IMPORTANT:
								Please "RESET" your TV after a Software update via network or USB, in order that the changes will be applied.
								Refer to the user manual on how to RESET the set to factory shipout condition.
								PLEASE NOTICE: individual channel list and personal settings will be deleted after a RESET.
	2013	19	BL502	B2	3.6.3c (low config)	---	---	CORE-SW Update for VESTEL 2013 TV models. Only main application will be updated.
		22	L1300A		3.6.3c (low config)	---	---	
		22	L1333/L1334	B/G	3.6.3c (low config)	---	---	IMPORTANT:
		22	L1337D/L1338D	B/G	3.6.3c (low config)	---	---	This SW update is NOT suitable to recover the set from "no power up / front LED blinking" symptom, as the Bootloader SW & Model related settings are not included.
		22	L1353/L1354	R	2.19z (mid config)	---	---	
		24	W1333/W1334	B/G	3.6.3c (low config)	---	---	To start the update, insert the USB stick ontaining the unpacked CORE-SW-file, and press: MENU + "1 5 0 5"
		24	W1337D/W1338D	B/G	3.6.3c (low config)	---	---	
		24	W1343	G	3.6.3c (low config)	---	---	Do not mix "low config" (Cable/T/Sat models) with "mid config" SW (T2 models only).
		24	W2300A		3.6.3c (low config)	---	---	
		32	L1334D	G	3.6.3c (low config)	---	---	
		32	L1338D	G	3.6.3c (low config)	---	---	
		32	L1343D	G	3.6.3c (low config)	---	---	
		32	L1347D	G	3.6.3c (low config)	---	---	
		32	L1353D	B/N	2.19z (mid config)	---	---	
		32	L1357D	B	3.6.3c (low config)	---	---	
		32	W1300A		3.6.3c (low config)	---	---	
		32	W1333/W1334	B/N	3.6.3c (low config)	---	---	
		32	W1333D	B/G/N	3.6.3c (low config)	---	---	
		32	W1334	G	3.6.3c (low config)	---	---	
		32	W1337D	B/G	3.6.3c (low config)	---	---	
		32	W1338D	G	3.6.3c (low config)	---	---	
		32	W1343D	G	3.6.3c (low config)	---	---	
		32	W1347D	G	3.6.3c (low config)	---	---	
		40	L1333	B	3.6.3c (low config)	---	---	
		40	L1333D	B/G	3.6.3c (low config)	---	---	
		40	L1334D	G	3.6.3c (low config)	---	---	
		40	L1337D	B	3.6.3c (low config)	---	---	
		40	L1338D	G	3.6.3c (low config)	---	---	
		40	L1343D	G	3.6.3c (low config)	---	---	
		40	L1347D	G	3.6.3c (low config)	---	---	
		40	L1353	B	2.19z (mid config)	---	---	
		40	L1353D	B/N	2.19z (mid config)	---	---	
		40	L1354	B	2.19z (mid config)			
		40	L1354D	B	2.19z (mid config)	---	---	
		40	L1357D	B	2.19z (mid config)	---	---	

If your model is not listed, there is no update available.
Please visit your local TOSHIBA Support website or Support Forum for further information.

Firmware update information for
Consumer Products (TV's, TV-Combis and BD-Players)

TOSHIBA
Leading Innovation >>>

Product Category:	Model year:	Size:	Modelname:	Countrycode:	Latest Version for Download	Network update available ?	Latest Version for Network update	Release notes (Fixed problems):
TV	**2013**	32, 39, 50	L2331D	G	1.05.05	---	---	Release notes 1.05.05: - fixes a problem with wrong EPG time in the territory of Spain (incl. Canary Islands).
		32, 39, 50	L2333D	G	1.05.05	---	---	
		32, 39, 50	L2337D	G	1.05.05	---	---	
		32	W2331D	G	1.05.05	---	---	
		32	W2333D	G	1.05.05	---	---	
		32	W2337D	G	1.05.05	---	---	
		32	W4333D	B	7.1.92.43.01.1	✔	7.1.92.63.01.1	IMPORTANT: If your Firmware version is older than 7.1.56.16.01.1 (otherwise the following has no relevance):
		32	W4333D	F/G	7.1.92.61.01.1	✔	7.1.92.61.01.1	If you update the set via network, this will happen via two separate, consecutive updates: No.1 update: will not change the version number.
		32/39/50	L4333D	G	7.1.92.61.01.1	✔	7.1.92.61.01.1	No.2 will update the set to the latest FW version 7.1.56.16.01.1
		32/39/50	L4353D	B	7.1.92.43.01.1	✔	7.1.92.63.01.1	--> as an alternative, use the USB update, which requires one single step.
		32/39/50	L4353	RB/RK	7.1.92.61.01.1	✔	7.1.92.61.01.1	
		32/39/50	L4353	N	7.1.92.43.01.1	✔	7.1.92.63.01.1	Version 7.1.92.43.01.1: - Fixes a problem with "SimplyTV" service in Austria
		32/39/50	L4363D	G	7.1.92.61.01.1	✔	7.1.92.61.01.1	- Fixed: "no wake up from STDBY witt ON-Timer, when power control is enabled"
		32/40	L6353D	B	7.1.92.43.01.1	✔	7.1.92.63.01.1	
		32/40	L6353D	F	7.1.92.61.01.1	✔	7.1.92.61.01.1	Version 7.1.92.61.01.1: - Maxdome PlayReady support
		32/40	L6353	RK	7.1.92.61.01.1	✔	7.1.92.61.01.1	- Improved Cloud connection stability - Stability improvements and regular bugfixes
		32/40	L6363D	G	7.1.92.61.01.1	✔	7.1.92.61.01.1	
		32/40	L6363D	N	7.1.92.43.01.1	✔	7.1.92.63.01.1	
		40/50	L7333D	G/F	7.1.92.61.01.1	✔	7.1.92.61.01.1	
		40/50	L7353D	B	7.1.92.43.01.1	✔	7.1.92.63.01.1	
		40	L7353/L7356	RK	7.1.92.61.01.1	✔	7.1.92.61.01.1	
		40/50/58	L7363	B	7.1.92.43.01.1	✔	7.1.92.63.01.1	
		40/50/58	L7363	F/G/RK/RB	7.1.92.61.01.1	✔	7.1.92.61.01.1	
		40/50/58	L7363	N	7.1.92.43.01.1	✔	7.1.92.63.01.1	--> please follow this instructions to install the update via network
		32/40	M6363D	G	7.1.92.61.01.1	✔	7.1.92.61.01.1	
		40/50/58	M8363D	G	7.1.92.61.01.1	✔	7.1.92.61.01.1	
		58/65/84	L9363D	B/G/F/N/S	7.11.80.35.05.1	✔	7.11.80.38.05.1	IMPORTANT: SW-version: 7.11.80.35.05.1 - 0211 This version supports input signals with 3840x2160@60Hz via HDMI ("HDMI2.0"). Unpack both files on an empty USB stick, unplug the power cable, insert USB stick to the TV and power on the set. Updates will be detected and run through consecutively.
		58/65/84	M9363D	G	7.11.80.35.05.1	✔	7.11.80.38.05.1	
	2014	32	L2433D / 2434D	G	1.05.15	---	---	v.1.05.15: fixes a channel scan problem in UPC cable network.
		32/40	L2453D/ 2454D	G/RB	1.05.15	---	---	
		40	L2432/2433/2434D	B/G	1.05.15	---	---	
		32	W2413D/W2432D	G	1.05.15	---	---	
		32	W2433D	B/G	1.05.15	---	---	
		32	L2443D	G	1.01.01	---	---	
		32	W2443D / W2444D	G	1.01.01	---	---	
		40	L2443D / L2444D	G	1.01.01	---	---	
		40/50	L2436D	B	1.00.44	---	---	
		40/50	L2456D	G	1.00.44	---	---	
		32/42/47	L6453D	B	8.1.97.10.01.1	✔	8.1.97.11.01.1	Release notes v. 8.1.97.10.01.1: - Stuttering audio on service BBC 2 HD LCN 102 AD Soundtrack (UK)
		32/42/47	L6463D	G	8.1.97.10.01.1	✔	8.1.97.10.01.1	- HbbTV (rtve.es Spain) HbbTv Streaming video not starting (Spain)
		42/47/55	L7453D	B	8.1.97.10.01.1	✔	8.1.97.11.01.1	v. 8.1.97.11.01.1:
		42/47/55	L7461D/7463D	G	8.1.97.10.01.1	✔	8.1.97.10.01.1	- MHEG not started when HbbTV is broadcast at the same time (UK Only)
				N/R	8.1.97.09.01.1	✔	8.1.97.09.01.1	
		42/47/55	M7463D	G	8.1.97.10.01.1	✔	8.1.97.10.01.1	

If your model is not listed, there is no update available.

Please visit your local TOSHIBA Support website or Support Forum for further information.

Firmware update information for
Consumer Products (TV's, TV-Combis and BD-Players)

TOSHIBA
Leading Innovation >>>

Product Category:	Model year:	Size:	Modelname:	Countrycode:	Latest Version for Download	Network update available ?	Latest Version for Network update	Release Notes (Fixed problems):
TV	2014	48	H1433D	B	3.6.3c (low config)	---	---	CORE-SW Update for VESTEL 2014 TV models. Only main application will be updated.
		48	H1453D	G	3.6.3c (low config)	---	---	
		40	L1400D	G	3.6.3c (low config)	---	---	**IMPORTANT:**
		48	L1433D	B/G	3.6.3c (low config)	---	---	This SW update is NOT suitable to recover the set from "no power up / front LED blinking" symptom, as the Bootloader SW & Model related settings are not included.
		48	L1435D	B	3.6.3c (low config)	---	---	To fix this problem refer to the related section of CP-portal under:
		48	L1443D	G	3.6.3c (low config)	---	---	https://portalcp.toshiba-tro.de/documents/10781/edcd53af-ee0b-4481-937d-dd3ab336d198
		48	L1453D	N	3.6.3c (low config)	---	---	
		24	W1433D	B	3.6.3c (low config)	---	---	To start the CORE-SW update, insert the USB stick ontaining the unpacked CORE SW-file, and press: MENU + "1 5 0 5"
		32, 40, 48	L3433D	G	3.3.6x *	✔	3.6.3c	
		32, 40, 48	L3441D	G		✔	3.6.3c	
		32, 40, 48	L3443D	G	3.3.6x *	✔	3.6.3c	
		40	L3444D	G		✔	3.6.3c	
		32, 48	L3447D	G	3.3.6x *	✔	3.6.3c	
		40, 48	L3448D	G		✔	3.6.3c	
		40, 48	L3451D	B/N	3.3.6x *	✔	3.6.3c	
		40, 48	L3453D	B/N/R		✔	3.6.3c	
		40	L3454D	B	3.3.6x *	✔	3.6.3c	
		40	L3455D	B		✔	3.6.3c	
		32	W3433D	G	3.3.6x *	✔	3.6.3c	
		32	W3443D	G	***	✔	3.6.3c	
		32	W3451D	B		✔	3.6.3c	
		32	W3453D	B/N/R		✔	3.6.3c	
		32	W3454D	B		✔	3.6.3c	
		32	W3455D	B		✔	3.6.3c	
		40, 48	L5435D	G		✔	3.6.3c	
		40, 48	L5441D	G		✔	3.6.3c	
		40, 48	L5443D	G		✔	3.6.3c	
		40, 48, 55	L5445D	G		✔	3.6.3c	
		55	L5447D	G		✔	3.6.3c	
		40, 48	L5453D	B	3.5.5F	✔	3.6.3c	
		40, 48	L5455	R		✔	3.6.3c	
		40, 48	L5463D	N		✔	3.6.3c	
		40, 48	T5435D	G		✔	3.6.3c	
		48	T5445D	G		✔	3.6.3c	
		40	T5455D	G		✔	3.6.3c	
		40, 48	T5463D	G/N		✔	3.6.3c	

If your model is not listed, there is no update available.
Please visit your local TOSHIBA Support website or Support Forum for further information.

**Firmware update information for
Consumer Products (TV's, TV-Combis and BD-Players)**

TOSHIBA
Leading Innovation >>>

Product Category:	Model year:	Size:	Modelname:	Countrycode:	Latest Version for Download	Network update available ?	Latest Version for Network update	Release Notes (Fixed problems):
TV with integrated DVD or Blu-ray Player	**2010**	19/22/26/32	DV733	G/R	v.2.05	---	---	
		19/22	DV734	G	v.2.05	---	---	
	2011	32/42	DB833	B/F/N	v1.57	---	---	
		32/42	DB833	G	v1.05	---	---	
	2012	32	DV502	B	v.0.6.8c	---	---	
		32	DV504	B	v.0.6.8c	---	---	
		19/23/26/32	DL933	B/F/G	v.0.6.8c	---	---	
		19/23/26/32	DL934	B/G	v.0.6.8c	---	---	
		19/22	DL502B	B	v.0.6.8c	---	---	
		22	DL504B	B	v.0.6.8c	---	---	
		22	DL702/704	B/N	v.0.6.8c	---	---	
		22	DL712B	B	v.0.6.8c	---	---	
	2013	19	DL502	B2	3.6.3c (low config)	---	---	CORE-SW Update for VESTEL 2013 TV-Combo models. Only main application will be updated to the latest available version.
		22	D1333	B/G/N	3.6.3c (low config)	---	---	
		22	D1334	B/G	3.6.3c (low config)	---	---	This SW update is NOT suitable to recover the set from "no power up / front LED blinking" symptom, as the Bootloader SW & Model related settings are not included.
		22	D1337D	B	3.6.3c (low config)	---	---	
		24	D1333	B/B2	3.6.3c (low config)	---	---	To start the update, insert the USB stick ontaining the unpacked CORE SW-file, and press: MENU + "1 5 0 5"
		24	D1333	G	3.6.3c (low config)	---	---	
		24	D1334	B/B2/G	3.6.3c (low config)	---	---	**Do not mix "low config" (Cable/T/Sat models) with "mid config" SW (T2 models only).**
		24	D1337D	B	3.6.3c (low config)	---	---	
		32	D1333D	B	3.6.3c (low config)	---	---	
		32	D1334D	B	3.6.3c (low config)	---	---	
		32	D1337D	B	3.6.3c (low config)	---	---	
		32	D1354D	B	2.19z (mid config)	---	---	
		32	DL1333	B	3.6.3c (low config)	---	---	
		32	DL1334	B	3.6.3c (low config)	---	---	
		40	D1333	B	3.6.3c (low config)	---	---	
Blu-ray Player			BDX1100K	B/E	v.62	---	---	
			BDX1200K	B/E	v.16	---	---	
			BDX1250K	B	v.22	✔	v.22	
			BDX1300K	B/E	v.20 / v.24	✔	v.20 / v.24	
			BDX2100K	B/E	v.33	---	---	
			BDX2250K	**B/E**	v.38	✔	v.38	
			BDX2300K	E	v.29	✔	v29	
			BDX2400K	B/E	v0.96	✔	v0.96	
			BDX3100K	B/E	v.43	---	---	
			BDX3200K	B/E/R	v.25	---	---	
			BDX3300K	B	v.28	✔	v.28	
			BDX3400K	B/E	v0.96	✔	v0.96	
			BDX4300K	B	v.30	✔	v.30	
			BDX4350K	B/E	v.39			
			BDX4350K	E	v0.96	✔	v0.96	
			BDX5300K	B	v.39			
			BDX5400K	B/E	v0.96	✔	v0.96	
			BDX5550X	**B/E**	v.1.14	✔	v.1.14	
			BDX6400K	B	v0.68	✔	v0.68	