




Kits de maintenance

Kit de dépannage alimentation des châssis TX807C/CS (90°)



35134120

Désignation	Qté	Position
1nF 5% 50V	1	CP027*
BZX55B16	1	DP021
BZX55C7V5	1	DP023
BZX55C27	1	DP027
1A6T 250V	1	FP001
TLP621 GR (D4-LF2 T)	1	IPO50
180KΩ 5% 0.430W	2	RP005-RP006
5.1Ω 10% 2.50W	1	RP008
1Ω 5% 2.50W	1	RP020
10Ω 5% 0.625W	1	RP052*
STP3NB90FP	1	TP020
BC337-40	1	TP022
BC856B	1	TP031*
BC846B	1	TP032*

* CÔTÉ CUIVRE

