




Kits de maintenance

Kit de dépannage alimentation des châssis ICC20



35134130

Désignation	Qté	Position
BZX55B15 (ZPD15)	1	DP053
2A5T 250V	1	FP001
VIPER20DIP	1	IP020
TEA2262	1	IP050
TLP621 GR (D4-LF2 T)	1	IP070
2.7Ω 5% 4.50W	1	RP004
100Ω 5% 0.750W	1	RP020
0.1Ω 5% 2.50W	1	RP052
STH13NB60FI	1	TP020
BC546B	2	TP026-TP080
BC337-40	1	TP057
MP315 (3.15A - 65V)	1	ZP009

