

SCHEMATIC DIAGRAM

Addendum: **Due to the low voltage used on B+. It has been noted that the 6AR5 is operating on the "knee" of a curve. Producing a distorted modulation pattern.**