



WFa - WFi = Waveforms to be observed at Waveform check points. (Shown in Schematic Diagram.)
 Input: PAL Color Bar Signal (with 1KHz Audio Signal)
 Receiving Ch.: E2 ch (48.25 MHz)
 Preset Mode: Press Picture Select button on the remote control unit, then press number "*" button.
 (Brightness—Center Color—Center Contrast—Aprox 70%)



CRT SCHEMATIC DIAGRAM

C984
X0PSU



NOTE: CHASSIS SCHEMATIC DIAGRAM NOTES.
1. ALL RESISTOR VALUES ARE IN OHMS. K=1000, M=1000K.
2. ALL CAPACITANCE VALUES ARE IN MICROFARADS UNLESS OTHERWISE NOTED. $\mu F = 10^{-6} F$