

$$P = \frac{U^2}{R}$$

$$U = \sqrt{P * R} = \sqrt{0,5W * 1250\Omega} = \sqrt{0,5VA * 1250 \frac{V}{A}}$$

$$\underline{\underline{U = 25V}}$$