



# Software Release Content

Model: LE810E / LX810E

Date: 29.12.2014

## **Software Version 1.12 [E1411051] - 25.12.2014**

- Slow reaction in case of HD+ programs

## **Software Version 1.21 [121E1301251] - 04.03.2013**

- Improved operation speed - The operation processing speed becomes comparatively slower when receiving a specific DTV broadcasts in Poland.

## **Software Version 1.20 [120E1207101] - 23.08.2012**

- Sound is interrupted when DD+ sound is heard by optical output
- Scramble may not be removed when TV set is started with CAM inserted
- Scramble is not removed when CAM of SMIT is plugged in and out

## **Software Version 1.16 [E1103311] - 26.04.2011**

- Improvement of Lip-Sync problem – sound has a delay to the picture

## **Software Version 1.15 [E1012111] - 11.12.2010**

- DVB-C Sorting changed from swap to move

## **Software Version 1.10 [xxx] - 26.07.2010**

- improved DVB subtitles
- improved playback of MP3 music files
- improved subtitles for Denmark
- EPOP deactivation after 30 min in Shop mode

## **Software Version 1.07 [E1004281] - 28.04.2010**

- Phenomenon „switch off by HD-channels“

## **Software Version 1.05 [E1004102] - 13.04.2010**

- improved for DVB-C 720p signal

## **Software Version 1.02 [E1003261] - 30.03.2010**

- certification of DLNA
- “de-juddering” improvement

## **Software Version 1.00 - 12.03.2010**

- Start with Mass Production