



IC90
MST7323S



SECRET
LGElectronics

THE SYMBOL MARK OF THIS SCHEMATIC DIAGRAM INCORPORATES SPECIAL FEATURES IMPORTANT FOR PROTECTION FROM X-RADIATION, FIRE AND ELECTRICAL SHOCK HAZARDS. WHEN STARTING IT IS ESSENTIAL THAT YOU MANUFACTURE SPECIFIED PARTS BY USING THE CRITICAL COMPONENTS IN THE SYMBOL MARK OF THE SCHEMATIC.